
				She	Sheet No.		Rev.
ARUP			271741-00		1		V5
		Member/Lo	Member/Location M		lember/Location		
Job Title	Ballinasloe Flood Relief Scheme	Drg. Ref.	Drg. Ref. Dr		ng reference		
Calculation	Hydraulics Report Appendix G - Prelim Blockage Assessment	Made by	MM	Date	10/05/2023	Chd.	AL



ARUP					271741-00 1			Rev. V5			
Job Title					Member/Location Member/Location   Drg. Ref. Drawing reference						
Calculation		/draulics Report Appendix G - Prelim Blockage Assessment				Made by MM Date 10/05/2023 Chd. AL					
	Ť			Maintenance			Cross sectional		Catchment		
Structure	ID D	esc	Historical evidence of blockage	regime	Trash sc	reen?	area	capacity	type	Preliminary Assessment	
1	ch an	tlas nannels nd 1lverts	The channel at Atlas Industries had a constriction which was subsequently removed. Arup noted on site visit that extensive sapling growth has established within the channel at Atlas, which would readily catch debris. Access bridge to domestic property at Dolans collapsed during 09 event. There is also a drainage pipe crossing in front of each opening under Church Road	Identified as a drainage distr (DD) channel maintained by GCC	ict – No		(Multiple sections) each > 3 m2	Circa 25 m3/s	(Branch channel of main Suck)	100% blockage used for Calibration runs. Assume unblocked in design runs considering works undertaken after 2009 flood and ongoing maintenance. Sensitivity analysis has been undertaken as part of the design runs.	
2	sti cu in ad to	ilvert let liggent	GCC confirmed that this culvert inlet has blocked in the past. Water overtops the inlet and flows through the cemetary onto Creagh Road. Water collects here until it drains away through the road gullies	No known regime. Inlet screen does no appear to be regularly maintained	<sup>ot</sup> Yes		0.64 < 3 m2 - without trash screen	(capacity of 450mm pipe) - 0.3 m3/s	Rural - trees along the channel but mainly grassland	It is proposed to carry out an assessment of a fully blocked screen as part of the options assessment	
3	h cu Po	allyhug Stream ilvert at ortnick rive	Yes – confirmed by GCC at PCD#1	Unknown – na a DD channel Inlet difficult access/inspect	to No		1.13 + 1.81 < 3 m2	<sup>600</sup> mm + 760mm pipes, that eventually converge into a single 600mm pipe - 2.16 + 4.86 m3/s	Rural - trees along the channel but mainly grassland	Model of this stream is uncalibrated. Blockage factor for design runs to be agreed with SG. Considering blockage history, a trash screen may be required – assessment to be completed as part of options development	
4	ey	7	Unknown. GCC was not aware of any history of blockage here	Identified as a drainage distr channel – maintained by GCC	ict No		Two arches, 9m2 each	Approx 11m3/s in baseline 1%AEP	Rural	It is proposed to carry out further assessment of blockage at this bridge as part of the options assessment. Bridge skew may promote some debris becoming trapped.	
5	lla br ch cu ur St	errymu an ranch nannel ilvert nder tation oad	Unknown. This culvert has been upsized in recent years	Not a DD channel but expected to be maintained as part of Derrymullen flood scheme.	No		currently 4.81 > 3 m2 - estimated	currently 7.23 m3/s	Rural - trees along the channel but mainly grassland	Blockage is unlikely to be a critical issue at this culvert in the context of the flood relief scheme. The risk of blockage is low given the size of the upgraded culvert and the hard angle at the upstream confluence with the Deerpark which will limit debris from getting into the watercourse.	
6		ast ridge	GCC confirmed that the bridge piers did catch large debris (trees) during the 2009 event which could not be cleared until after the event. The sluice gates also caused a major blockage, but this issue has since been resolved with the works in 2012. There is also a drainage pipe crossing on the downstream face which partially obscures the bridge eyes	Unknown	No		(Multiple sections) each > 3 m2	>285m3/s in baseline 1%AEP	Rural - wooded	It is proposed to carry out further assessment of blockage at this bridge as part of the options assessment, as the bridge acts as a hydraulic control on design flood levels upstream and given the potential consequences of a blockage.	
7	br		Unknown. GCC was not aware of any history of blockage here	Unknown	No		25.3 -> 16 m2 of effective area (accounting for skew angle) > 3 m2	39 m3/s	Rural - trees along the channel but mainly grassland	It is proposed to assess blockage at this bridge given the proximity of vulnerable properties at Derrymullen.	
8	br	ailway ridge Suck)	Unknown	Identified as a drainage distr (DD) channel maintained by GCC	ict – No		(Multiple sections) each > 3 m2	>330m3/s in baseline 1%AEP	Rural - trees along the channel but mainly grassland Kurar - trees	Blockage is unlikely to be a critical issue at this bridge in the context of the flood relief scheme given the large area of the bridge openings, its position on a straight section of the Suck, and its lack of history of blockage	
9	Cl	ld hannel ridge	Unknown. GCC was not aware of any history of blockage here	Unknown	No		TBC	TBC	along the channel but mainly	It is proposed to assess blockage at this bridge given the proximity of vulnerable properties at Derrymullen.	