

Appendix 13.4

Glashaboy River

Site Inspection -

Plates 1-53



Plate 1: Bleach Hill Stream, looking southwest



Plate 2: Bleach Hill Stream, entering culvert under road, looking southwest



Plate 3: Sallybrook Mill, south elevation



Plate 4: Sallybrook House, east elevation



Plate 5: The Glashaboy River to the west of Grandon's Garage with rock armour visible upstream, looking north



Plate 6: Mill race 3 opening in Grandon's Garage showing remains of sluice gate, before entering culvert, looking southeast



Plate 7: Mill race 3 in Grandon's Garage property, emerging from culvert, looking northwest



Plate 8: Mill race 3 on the southern side of R639, north of Glansillagh Mill (CO063-094)



Plate 9: Unnamed channel around Sallybrook House entering the Glashaboy River, looking west




Plate 10: Cois na Gleann Stream, looking west



Plate 11: Stone lined well around Cois na Gleann Stream, looking south



Plate 12: Cois na Gleann Stream along the northern end of pasture field before converging with Glashaboy, looking east



Plate 13: Field adjoining R639



Plate 14: Wall along western side of field



Plate 15: Hazelwood Avenue Bridge and adjoining green area where relief channel will be constructed, looking north



Plate 16: Overgrown area to east of bridge where relief channel will be constructed, looking north



Plate 17: View downstream from Hazelwood Avenue bridge



Plate 18: View of earthen bank in Glanmire Shopping Centre, looking north



Plate 19: View of bridge in Glanmire Shopping Centre, looking south




Plate 20: View of gabions against eastern river bank at supervalu building, looking northeast



Plate 21: View of R639 where Springmount Stream is culverted. The stream re-emerges behind the hedgerow parallel to the road within the trees



Plate 22: Open channel of Springmount Stream north of Meadowbrook, looking north



Plate 23: Springmount Stream at convergence with Glashaboy River, looking northwest



Plate 24: View upriver from Riverstown Bridge, looking north



Plate 25: Western bank approaching Riverstown Bridge



Plate 26: Wall parallel to river in Meadowbrook



Plate 27: Path and green area to west of Riverstown Bridge



Plate 28: Wall to east of Riverstown Bridge



Plate 29: Western elevation of Glyntown Bridge at the confluence of the Butlerstown and Glashboy



Plate 30: Southern elevation of unnamed single arch road bridge over Butlerstown River



Plate 31: Northern elevation of Copperalley Bridge in grounds of Riverstown House



Plate 32: Lawn to the east of Riverstown House where embankment will be constructed and Riverstown House, looking northwest



Plate 33: Glenmore Stream eastern section with Brooklodge Grove Road to south (right). Opening to the rectangular culverted channels are visible at bottom right, looking east



Plate 34: Eastern culvert opening, north-facing elevation



Plate 35: Eastern culvert opening, showing dry south-facing elevation



Plate 36: Riverstown Bridge, southern elevation



Plate 37: The Glashaboy in John O'Callaghan Park, looking east



Plate 38: Stone faced bank, looking east